		•	មន្ទីរ៉ឺស៊ីស ប៉ុន្តាំទី។ មន្ទីរីស៊ីស ប៉ុន្តាំទី។ ស ស ស ស ស ស ស ស ស ស ស ស ស ស
Approved For Release 2002/06/1	8 : CIA-R5印格B00836R000300020030		en Sell and
	The rope section of	The second section of the	Company of the compan
The second secon	The composition of the control of th	A Company of the second	
25X1	Α		The second secon
	- CONTRACTOR	PRICRYTY	1965年,第186 章 的时期的280章(1955年) 1
- 1460 3 - 1		A COMMENT OF THE PROPERTY OF T	Continue of the continue of th
TOR-05207 20 FEB 66	***		IN 89241
25X1A 25X1A	505	1-10	25X1A
PRIORITY		CSEC	TO THE TOTAL CONTROL OF THE PROPERTY OF THE PR
25X1	A ;		
SESTERNING ACCIDE	NT INFORMATION ARTICLE 672.		
·	•		

- RETURNED TO ACCIDENT SCENE SAT HODY (19TH) AND HAVE THE FOLLOWING PRACMENTARY INFO TO REPUBLE:
- A. TWO WITNESSES SAW ATROPATE AT OR SHORTLY BEFORE FIRST TOUGHDOUN. BRIEF OF THEIR REPORT SUPPORTED BY MEASURED WHEEL MARKS, HROKEN TREES, AND CONTACT WITH FIRST BUILDING IN VILLAGE ESTABLISHES FOLLOWING PATH OF AIRCRAFT FROM TOUCH DOWN TO FINAL HEST: FIRST TOUCH DOWN WAS ALONG A LINE ADDROX COO POOT LLEL TO 🖦 SIDE OF NORTH SOUTH RIBBOUT AND APPROX 95 FEET BEYOND THE SOUTH END OF THE RUNWAY. FROM THIS PLINT ON AIRCRAFT WAS ON THE GROUND FOR 53 FT., OFF GROUND FOR 20 FT., ON GROUND FOR 17 FT., TO SCHED GROUND AT PLUS 152 FT., TOUCHED GROUND AT PLUS 27 FT., OFF SECURD FOR PLUS 135 FT, ON THE CROSSED FOR 438 FT, AIRBORN FOR 84 FT., OUT THROUGH TOPS OF TREES PERPENDICULAR TO FLIGHT PATH CALTITIES APPROX 15 FT)., ATR BORNE FOR PLUS 80 FT., STRUCK 4 OR 5 ··· CONTINUED.

Approved For Release 2002/06/18 : CIA-RDP74B00836R000300020030-3

THREE STORIES OF OTHER TENED THE PROPERTY CARRIES OF THE THREET, HOW BELL.

'	X1A	7.4D000000000000000000000000000000000000	Ų	
Арр	oroved For Release 2002/06/18 : CIA-RDP7	/4B00836R000300020030	PAGE TWO	
	MORE TALE TOPS AT ABOU			วิริล เซเซร อ ล์
ļ	BAS AT STANCK LIGHT OR TELEP			
	CONTINUED IN THE AIR FOR 65			
	AND CAME TO REST IN VILLAGE			
25X1				•
25X1A	Leave to the second		HHLISHED TRAT	·
23X IA	ATRONATO.	RECEIVED ANY I	RADIO INFO OR OBS	ERVED
				_
i { }	A COLUMN TO A COLUMN TO SECULT OF THE SECURT OF THE SECURE OF THE SECURIT OF THE			25X1A
	THIS TASK WILL BE COMPLETED (ON SUNDAY. BY LAT	E AFTERNOON SAT	
	IT WAS APPARENT THAT WE PROBE	ABLY VONT BE ABLE	TO LIFT FUSELAGE	
F.	AND ENGINE AS PREVIOUSLY PLAN	NNED. LOGRE NOW L	THE ENGINE WILL	
•	HAVE TO BE PEELED FROM FUSELA	AGE SECTION AND LI	FTED SEPARATELY.	
· ?	ENGINE LOOKS TO BE IN FAIRLY	GOOD COMETTION.	SALVAGE ACTIONS	
i I	WILL BE COORDINATED WITH ACCI	IDENT TEAM SUNDAY	AFTERNOON	
! i	AND IF THEY CONCUR WILL COMME	INCE REMOVAL ON MO	MDAY AREA MARA	
051/4 4	OF INTEREST TO ON HO	ONDAY OR THESDAY N	AND MONE III	IM S
25X1A	D. UNDERSTAND FROM THE	SETTER AN CONTRACTO	IGHI .	
:	ONE PATALITY AND FIVE INJURIE	C TO CTIC SALURDAY	THAT THERE WAS O	HILY
	THE SECOND FATALITY REPORTED	e du tavallan PER:	SOWNEL. INFO RE	
İ	THE SECOND FATALITY REPORTED :	LAIL IKUR SDAY WAS	IN ERROR.	
*1A	THEIR ARRIVAL AND TAKE	ACCIDENT PEAM IMME	CDIATELY UPON	
.	THEIR ARRIVAL AND TAKE THEY TO ON SUMDAY AFTERNOON.	O ACCIDENT SUENE V	FIA	25X1A
i	TONCAME WAS HE	eld satureay after	NOON. SEPARATE	
X1A	SENT FROM		D LAC PERSONNEL.	:
	CONTINUED			

Approved For Release 2002/06/18 : CIA-RDP74B00836R000300020030-3

	25X1A 25X1A pproved For Release 2002/06/18 : CIA-RDP74B00836R000300020030-3
	IN ESSAL TOPSECHES PAGE THREE
25X1A	PER SUGGESTION, WHICH I CUNCURRED WITH, FOR SECURITY 25X1A
25X1C	SEASONS,
25X A	S. WAS INFORMED BY ON SAT NIGHT THAT
	THAT THERE WOULD BE NO OPS MISSIONS UNTIL FURTHER NOTICE. 25X1A
	I CONSIDER THIS PROBABLY NORMAL POSITION AT THE MOMENT
•	AND DO NOT KNOW THE EXACT TENOR IN WHICH STATEMENT MADE.
•	WELL NEEP YOU INFORMED THIS REGARD WHEN I HAVE BETTER FEEL FOR
\	THEIR POSITION AND ATTITUDE. MUCH WILL DEPEND I'M SURE ON THE
	INVESTIGATION OUTCOME ON THE REPORTED OVER TEMP. WHETHER OR NOT
	A RELIGHT WAS ATTEMPTED AND FURTHER ANALYSIS OFACTIONSACTIONS
	AND FLAME OUT LANDING ATTEMPT.
i	END OF MESSAGE

TOPSECRET